# Weathertzation Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/15015SE-6076/1

Work Order Type: Weatherization

Audit Name: 15015SE-6076AUDIT

**CLIENT INFORMATION** 

Client Name: NA Address:

**Client ID:** 15015SE-6076 Turtletown, TN 37391

Alt. Client ID: Polk

**CLIENT CONTACT INFORMATION** 

NA Applicant/Person of ✓ Site built

Record

Built approx 1984 Approx 1008 sqft

<u>AGENCY INFORMATION</u>

Agency: Southeast Tennessee Human Resource Agency Agency Phone: (423) 949-2191

**Address:** 312 Resource Rd. **Fax:** (423) 949-4023

Agency Contact: Bloodworth, William D. Work Phone:

**Cell Phone:** (423) 505-4585

Email Address: Darblood@comcast.net

Company Name & License Number:	
Contractor's Signature:	

#### COMMENT

### Measures

Measure 1 DWH Pipe Insulation				Components						Inspected
C	Comment									
						Estimated	d		Actual	
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation		DHW Pipe Insulation	Linear Foot	10					
			Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor		DHW Pipe Insulation	Each	1					
3	Other		DHW Pipe Insulation	Each	1					
(	Other Detail									
					Measure	e Sub Total:		,	Sub Total:	
	Measure 2	Attio	: Ins. R-30			Componer	ate Attic			Inspected
		Attic	ins. K-30			Componer	ns Auc			Inspected
C	Comment				Estimated			Actual		
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation		Attic Insulation - Blown Fiberglass - R-30	SqFt	1008					
(	Other Detail				1					1
					Measure	e Sub Total:		,	Sub Total:	
	Field Notes:									

	mproper Venting of Bat aust Fan	hroom		Componen	ts			Inspected
	nts installed to outside of ent A- Standards for Wea			•		Field		
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Bath Vent w/ Piping to Outside	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 4 Fix C	Other Water Heating Pro	blem		Componen	ts			Inspected
Comment								
				Estimated				
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
	Romex connector							
2 Labor	Labor	Each	1					
	Install Romex connector							
Other Detail								
			Maasur	e Sub Total:			Sub Total:	
Field Notes:			measur	c oub rotur.				
	all Bathroom Exhaust Far fan equal to Nutone Mod nt.		RFT. M	Component ust be energ		Title 24		Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Health and Safety	Bathroom exhaust fan	Each	1					
	Exhaust fan equal to Nutone Model # 769RFT. Must be energy star or Title 24 compliant.							
2 Labor	Labor	Each	1					
Other Detail								
Other Detail								
							Sub Total:	
			Measur	e Sub Total:			Sub Total.	
Field Notes:								

I	Measure 6 Pres	sureRelief Piping Neede	ed		Componen	ts			Inspected
C	valve tha ran throu	eater must have a copper at should terminate throug ugh wall and terminate wit ws may be used.	h the floo	or. If th	is is not pos of the ground	sible pip . No mo	e can b		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
		6' of copper pipe to extend no further than 6" above floor.							
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

-	or Barrier Needed ement/Crawlspace)			Componen	ts			Inspected
walls and earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea rization Materials and So	securely ms. Refe	fastene to Atta	ed. Must be achment A- S	cleated c	lown to		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	1008					
2 Labor	Labor	SqFt	1008					
Other Detail						,		
			Measure	e Sub Total:		] ;	Sub Total:	
Field Notes:								
		Work O	der Gra	nd Total:		Gran	d Total:	